



Heritage Preservation
Department of Planning and Economic Development
1400 City Hall Annex
25 West Fourth Street
Saint Paul MN 55102-1634
651-266-9078

Office Use Only
File #:
Date Received:
Date Complete:
Tentative Hearing Date:

HISTORIC USE VARIANCE APPLICATION

Property Information			
Address/Location: 445 Smith Avenue, Sa	aint Paul MN 5	55102	
Legal Description: E1/2 of L13 and L14, E	BI 9, N. of the S	. 60' of same, Leech's Add'n	
Current Zoning: R4- One-Family			
Proposed Use: T2- Traditional Neighbor	rhood		
Name of Owner: Thomas S. and Ann M. (if different from applicant)		-	
Contact Person: Thomas S. Schroeder (if different from applicant)		Phone: (612) 385-8838	_
Applicant Information			
Name: Thomas S. Schroeder			
Email: Tom.Schroeder@FaegreBD.com		Phone: (612) 385-8838	_
Address: 194 McBoal Street			
City: Saint Paul	State: MN	Zip: <u>55102</u>	

The applicant must fill out the attached Historic Use Variance application checklist and attach any necessary documents.

NOTE: If the project will result in any exterior modifications or additions, a Heritage Preservation Design Review Application must be submitted and reviewed by the HPC prior to the Historic Use Variance Application submittal.





Heritage Preservation
Department of Planning and Economic Development
1400 City Hall Annex
25 West Fourth Street
Saint Paul MN 55102-1634
651-266-9078

HISTORIC USE VARIANCE APPLICATION

The applicant must fill out the Historic Use Variance application checklist by placing a check mark in the boxes under the 'Applicant' column and attaching the accompanying documents. The 'Staff' column is for staff to verify that your submittal requirements have been met. 15 physical sets of application materials must be provided with application. All application materials must also be provided electronically on a CD or USB drive to allow for web posting for public hearing.

cant				
Applicant	Staff			
/		1)	Descrip	ption of the proposed use and its consistency with the structure's historic use.
√	П	2)	Descrip	ption of any exterior modifications to the structure, property, and site including an
			assessn	nent of the impact of these modifications on the historic integrity of the site.
✓		3)	Descrip	ption of all interior architectural features unique to the historic period.
√		4)	Site pla	an
√		5)	Photos	of existing conditions
\checkmark		6)	11" x 1	7" Architectural plans drawn to scale that include any proposed modifications.
/		7)	Inform	ation supporting the following findings. (Do not simply rewrite the findings. You
_	_		must d	iscuss why you believe the findings below can be made for your request.)
\checkmark			a.	The proposed use is reasonable and compatible with the historic use(s) of the site
				or that the new use is consistent with Legislative Code Chapter 73.04(5).
\checkmark			b.	The proposed use complies with the adopted preservation program and the
				United States' Secretary of the Interior's Standards for Rehabilitation.
\checkmark			c.	The historic use variance is necessary to alleviate practical difficulties unique to
				the heritage preservation site that prevents its use in a manner consistent with its
				historic use or that the new use is consistent with Legislative Code Chapter
				73.04(5) and that these difficulties were not created by the applicant.
\checkmark	Ш		d.	The proposed use is compatible with existing uses in the surrounding area and
				the underlying zoning classifications in the area.
\checkmark			e.	The proposed use is consistent with the comprehensive plan.
1		8)	1 CD o	or USB drive of application materials
/		9)	15 phy	sical sets of application materials
certif	y that	Ih	ave con	upleted and have included all material checked above in the application submittal.

Date: 723 15

Applicant Signature: 1

Attachment to HUV Application Form

Project Background:

This project involves the historic restoration of both a building and a business.

The Anthony Waldman House, also referred to as the Stone Saloon, was built in the fall of 1857—six months before Minnesota became a state, nearly four years before the Civil War began, and at a time when fewer than 10,000 people lived in the City of Saint Paul. The building is the City's the oldest surviving commercial building. Its vernacular design, solid limestone masonry and early period of construction provide the basis for its pending historic designation by the City of Saint Paul. Most relevant for purposes of this application, the Stone Saloon is one of only a few surviving Civil War-era saloon buildings in the region—and it is a very special one at that. Waldman's was a "lager beer saloon."

German lager beer (as distinguished from darker, heavier Yankee ales of the period) took Minnesota Territory by storm in the 1850s. By the time the Stone Saloon was built, Saint Paul had 12 breweries, all but two of which manufactured lager beer. At first these breweries served almost exclusively the local market, where much of the consumption took place in Saint Paul's lager beer saloons. In 1860 the growth of lager breweries and proliferation of lager beer saloons received an unlikely boost from the enactment of Minnesota's Lager Beer Act, a blatantly protectionist and oddly pro-Temperance measure that exempted the manufacture and sale of lager beer (and lager beer alone) brewed or sold within the State from all forms of licensure, sales tax or bonding requirements. Even when the Act was repealed in 1863, City ordinances continued to grant favorable treatment to lager beer saloons by licensing them separately from all other saloons, affording the former much-reduced fees and an exemption from the normally stiff enforcement bonds.

In addition to German-Americans' growing political power (which was bolstered by the election in 1860 of President Lincoln and many Republicans in Minnesota), the special status bestowed upon lager beer saloons reflected the distinctive drinking culture brought by Germans to their adopted homeland. In contrast to most Yankee saloons, which primarily served hard liquor and offered little by the way of food, lager beer saloons served beer almost exclusively, a variety of foods, and often hosted musical events or other forms of entertainment. For these reasons, and because lager beer's lower alcohol content made it more socially acceptable to teetotalers in the age of Temperance, lager beer saloons gained the reputation of being more family-friendly and community-oriented. More than just places to drink, nineteenth-century German-Americans saw their lager beer saloons as a kind of social institution.

This project seeks to recreate the conditions and attributes of a mid-nineteenth-century German lager beer saloon, in a meticulously restored building that once housed just such an establishment. Importantly, the term "saloon" is used here only in a limited, historical sense. Analogous to Anthony Waldman and other lager beer saloon proprietors of the 1850s and 1860s, we do not seek a variance for a liquor license, but for a beer-only tap house/micro-brewery. Substantial and costly exterior restoration work has already been completed on the roof, front façade and exterior stone masonry of the building, re-exposing the historic commercial façade which was filled in with stone work after 1885. (See "Before and After" image, Tab 1). Through our continued research and attention to detail, we seek to give people the chance to experience first-hand this unique historic, architectural and cultural asset; to create a landmark

gathering place for the West 7th Street and surrounding communities; to fuel the interests, discussions and intellectual curiosity of architects, historians and preservationists everywhere; and to showcase the City's adeptness at leveraging its historic assets for redevelopment purposes.

This project and the proposed historic use variance has widespread public support, including the written support of Historic Saint Paul, Preservation Alliance of Minnesota, the Fort Road Federation/District 9 Council, and the Little Bohemia Neighborhood Association (see Letters of Support, **Tab 2**). The boards of each of these organizations have toured the site first-hand, and viewed the same materials submitted along with this application. As their support attests, and as has already been demonstrated by the enactment of the City's first historic use variance ordinance—prompted by this project—the Stone Saloon is small building with a potentially big footprint. We thank you for your consideration of the responses that follow.

1) Description of the proposed use and its consistency with the structure's historic use.

We propose to use the Stone Saloon as a licensed tap house/micro-brewery, producing and serving historically inspired German-American beers similar to those brewed in Saint Paul during the state's Territorial and Civil War periods. Non-alcoholic sodas such as birch and root beers will also be produced and served on premises, as well as coffee and teas. True to most historic lager beer saloons, we will offer a limited menu of assorted cheeses, charcuterie, pickled and soured vegetables, artisan breads, German pretzels and mustards, and deserts. We hope later to expand the menu to include grilled and boiled wursts, leberkase, German potato salad and soups/stews. Other than filling a limited quantity of 64-ounce growlers, there will be no packaging, distribution or off-site sale of beer or other beverages from the site. (This is different from Bad Weather Brewery, whose business model includes off-site sales/distribution.)

The interior furnishing of the Stone Saloon will be guided by descriptions and inventories of 1850-60s lager beer saloons found in a variety of primary sources, including courthouse, real estate, newspaper and other records. Our current collection includes period saloon/steamboat chairs, saloon tables, pewter lighting fixtures and numerous other artifacts of the era. Wherever possible, modern building code, accessibility, food safety, sanitation and licensing requirements will be satisfied by blending today's technology with character-defining historic treatments (for example, the nine-light window sashes in the commercial façade are comprised of codecompliant safety glass laminated to distorted hand-blown glass panes). Most importantly, impacts on the integrity of the interior of the historic structure will be minimized by locating most modern functions (brewery, kitchen, restrooms, utilities, storage, etc.) in a new separate structure to be built in the backlot and connected to the historic structure by a vestibule. This design ensures that the proposed use will be consistent with the building's historic use to the maximum degree possible.

2) Description of any exterior modifications to the structure, property, and site including an assessment of the impact of these modifications on the historic integrity of the site.

Stone portion: The 1857 stone portion at the front-lot will not be altered from its state at designation. A handicap accessible ramp will be installed at the sidewalk to the south, leading to an entrance at the south of the rear wood frame addition. A period-appropriate hand-painted sign complying with the Preservation Program developed by the City/HPC will be mounted at the

front commercial cornice. Bicycle racks will be installed where permitted by Public Works or on site if not permitted. The location and design of either option will be done in consultation with City/HPC staff.

Rear wood frame addition: With the approval of the City/HPC, the rear wood frame addition to the stone building will be reconstructed in accordance with the Secretary of Interior's Rehabilitation Standards and the Preservation Program for the site. (See rear addition plans and elevations, enclosed). Our decision to replace the rear addition "in-kind" has been informed by an extensive structural analysis by a qualified engineering firm. This analysis concluded that too much existing material—approximately 80 percent—would need to be replaced or strengthened with additional new material for repair to be feasible and prudent. (See Tab 3 - Align Structural, Inc. report dated 8/19/14; Memo by Historian-Consultant Bob Frame to Amy Spong, Christine Boulware, HPC dated 8/19/14). Nevertheless, replacement of the rear addition "in-kind" will yield a reconstructed addition with the same footprint, floor levels, ceiling heights, roof peak, and interior stairway placement as the existing structure. As show in the enclosed plans and elevations, the exterior features of this addition have been designed in the Greek Revival style prevalent during the 1850s and 1860s and evidenced both at this site and others included within the Stone Saloon's thematic designation. Although the submitted plans alter the roof pitch of the circa-1885 addition now in place, the reconstructed roof pitch will match the pitch of the predecessor addition's historic, Greek Revival roof pitch (6"/12") which is clearly traced in the masonry along the rear façade of the stone building.

Newly constructed building: A newly building will be constructed at the backlot and connected to the historic structure by a vestibule. The new building will house the brewery equipment, kitchen, restrooms, storage, utilities and office. (See site plan and elevations, enclosed). The placement of these functions in a newly constructed building minimizes the impacts they might otherwise have on the integrity of the historic building. The new building and its connecting vestibule are designed to clearly differentiate themselves from the historic structure, while keeping with the character of the site and of other 19th accessory buildings in the area. The positioning of the new building at the backlot and the use of landscaping effects (including hop trellises along the south and east exterior walls of the new building) will keep the spotlight on the historic structure in front. Every design and engineering effort has been made to minimize the scale of the new addition, including employing stacked, horizontally mounted fermentation and lagering tanks, a ceiling trolley to maximize storage efficiency, and a highly compact kitchen preparation area. Finally, the new building will occupy nearly the identical footprint of an alley-house that once sat in the same location behind the Stone Saloon from 1874 to 1898. The positioning of the new building therefore relates to the historic context of the site during the final eleven years of the Waldmans' residency.

No other modifications are proposed to the site which would impact its historic integrity. Importantly, we have secured all off-street parking required by code at a location other than the historic site, further minimizing impacts on the site's integrity. This means that there will be no parking on the historic property at all. (See parking layout, enclosed.)

Moreover, the owners of the tap room/brewery Bad Weather Brewery immediately across the alley have agreed to work with us to consolidate supply purchases and deliveries, as well as to

share the use of their wood-screened waste disposal pad and trash hauling and recycling services. (See Letter of Joe Giambruno and Zac Carpenter, Bad Weather Brewing, **Tab 4**).

3) Description of all interior architectural features unique to the historic period.

The Pioneer Era Houses context study cited in the Stone Saloon's historic designation established the temporal parameters for the historic period included in the thematic designation as 1854-1880. The stone portion of the Stone Saloon retains the following architectural features and materials from this historic period:

- original tongue-in-groove pine flooring on both first and second levels;
- original staircase between first and second levels;
- two original two-panel doors, with some original hardware; and
- one original window casing and sill in second level, south window.

As described in the designation, the rear wood frame addition post-dates the Pioneer Era, and in any event no longer contains any historic architectural or character-defining interior features.

4) Site plan

See enclosed.

5) Photos of existing conditions

See Tab 5.

6) 11" x 17" Architectural plans drawn to scale that include any proposed modifications.

See enclosed.

- 7) Information supporting the following findings.
 - a. The proposed use is reasonable and compatible with the historic use(s) of the site or that the new use is consistent with Legislative Code Chapter 73.04(5).

As discussed above, the proposed tap house/micro-brewery use closely approximates the historic business use of the site as a neighborhood beer-only saloon (in the historic sense) offering limited food service. The addition of a sensitively designed structure in the backlot is a reasonable accommodation to modern restrooms, equipment and utilities.

b. The proposed use complies with the adopted preservation program and the United States' Secretary of the Interior's Standards for Rehabilitation.

Aside from modifications dictated by public safety and handicap accessibility (e.g., the handicap ramp to the south) the most material modification caused by the proposed use is the new construction on the backlot. In keeping with Secretary of

Interior's Rehabilitation Standards and the accompanying Rehabilitation Guidelines pertaining to new additions to historic structures, the new building and vestibule are designed in a manner that differentiates them from the historic structure, while being compatible with the massing, size, scale and features of the site and its surrounds. The roof peak of the new building is lower than the roof peak of the historic stone building, and the roof pitch matches that of the reconstructed rear wood frame addition as well as that of the historic stone building's hipped roof (both having a pitch of 6"/12"). The location of the new building at the backlot and future landscape treatments (including hop trellises along the south and east exterior walls of the addition) will keep the spotlight on the historic structure in front. (See Rehabilitation Standard 9; see also Secretary of Interior Rehabilitation Guidelines for New Additions). The north and west elevations of the new building will be visible only from the alley. Moreover, because Smith Avenue and the sidewalk in front of the Stone Saloon lie approximately 3' below the grade of the historic site, the lowered sightlines from the public right-of-way enhance the prominence of the historic stone structure at the front of the lot relative to the new construction to the rear.

Finally, the new structure allows for reversibility. In the event that the proposed use ever ceased, the new addition and its connecting vestibule could be removed without impairing the form or integrity of the original historic structures, or the historic site as a whole. (See Rehabilitation Standard 10)

c. The historic use variance is necessary to alleviate practical difficulties unique to the heritage preservation site that prevents its use in a manner consistent with its historic use or that the new use is consistent with Legislative Code Chapter 73.04(5) and that these difficulties were not created by the applicant.

The Stone Saloon was designed, built and originally used as a commercial property. As established in its designation, it was historically used as a lager beer saloon. The practical difficulty that prevents the Stone Saloon from being used in a manner consistent with this historic use is the parcel's residential zoning classification (R4). This difficulty was not created by the applicant.

A broader practical difficulty is the initial and continued expense of the historic preservation and rehabilitation of the Stone Saloon. A historic property cannot be preserved and maintained without a viable and ongoing means of support, regardless of its level of significance.

This project began with a registered Vacant Building that had several outstanding nuisance and abate orders, extensive structural issues, and no independent water or sewer line (both T-ed off the adjacent, separately owned parcel). The adjacent parcel had to be acquired in order to access these essential utilities and provide for their upgrading. While stonemasonry in general has excellent longevity, stonemasonry repair after nearly 160 years of weathering and inappropriate maintenance can be (and in this instance, has been) extremely costly. For the present applicant this project has thus far been both a "labor of love" and "leap of faith," but the complete restoration/rehabilitation of this historic site,

as well as its ongoing maintenance, must ultimately be sustained by a more rational economic calculus.

The proposed use as a beer-only tap house/micro-brewery is minimally tailored to leverage the unique history of this building for a sustainable, income-producing use. The proposed use not only respects the building's history, but allows the public to share in it. In comparison, use of the building as (for example) a private residence would not attract the level of investment required to rationally undertake the same level of rehabilitation, and would not yield the same "public good" of community access to this unique and historic lager beer saloon. The grant of a historic use variance in this instance would be in keeping with Policy 5.5 of the Historic Preservation Plan, part of the Saint Paul Comprehensive Plan, which establishes a goal to "develop land use and regulatory incentives to make it easier and more feasible to rehabilitate" historic resources by applying "an ordinance that allows historic variances in order to alleviate undue hardships created by the historic character of designated properties."

For these several reasons, a historic use variance for tap house/micro-brewery use is the minimum needed to enable this property to be used in a manner that will have the least impact on its historic character and the character of the surrounding area. (Leg. Code § 61.601(g).

d. The proposed use is compatible with existing uses in the surrounding area and the underlying zoning classifications in the area.

The use of the Stone Saloon as a tap house/micro-brewery is similar (although smaller in scale) to the current use of a much larger and partly contiguous TN2 site immediately across the 16'-wide alley to the northwest, newly operating as Bad Weather Brewery. Degidio's Restaurant and Bar operates with a full liquor license in B2 zoning approximately 330 feet to the northwest, across West 7th Street from Bad Weather Brewery. Garafolo's Automotive Repair operates from a T1 parcel approximately 180 feet down the alley from the Stone Saloon. A flat-roofed former factory building turned used clothing store turned artists' studio lies immediately across Smith Avenue (State Highway 13) to the north of the Stone Saloon. Bonfe's Auto Repair lies approximately 300 feet north and across Smith Avenue in T2 zoning. Within the immediate neighborhood and along West 7th Street, numerous T1-, T2-, B2- and B3-zoned parcels sit immediately adjacent to R4 and other residential zoning classifications.

The proposed use for the Stone Saloon is compatible with this mix of commercial and residential zoning classifications in the immediate and surrounding areas. The applicant is a 25-year resident of the neighborhood, living within approximately 250 feet of the Stone Saloon. He fully intends to address any concerns that may arise from the Stone Saloon's operations.

e. The proposed use is consistent with the comprehensive plan.

The site of the Stone Saloon is within an Established Neighborhood of Uppertown/West 7th proximate to the Mixed Use Corridor of West 7th Street. The

comprehensive plan defines Established Neighborhoods to include "scattered neighborhood-serving commercial, service and institutional uses at the juncture of arterial and collector streets." (LU-1) Mixed Use Corridors "include areas where two or more of the following uses are or could be located: residential, commercial, retail, office, small scale industry, institutional and open space uses." (LU-1) The District 9 Area Plan supports "nodes' of retail businesses at the intersections of West 7th and Kellogg, Smith, St. Clair, Jefferson, Randolph, and Montreal/Lexington." (p.4) It further states that "when possible, storefronts that have been altered should be restored to, or close to, their original character. In some cases, the original building fabric may be found behind the alterations." (p.7) Although the proposed use is not permitted by the underlying zoning of its individual parcel, it is broadly consistent with these principles set forth in the city's comprehensive and area plans.


The Historic Preservation brochure for the Saint Paul Comprehensive Plan, cited in the preamble to the historic use variance ordinance being applied to this application, states that "the character and design features of historic properties make them desirable for new uses that recognize the community's special identity." Ironically, in this case it is an old use that recognizes the West 7th Street neighborhood's special identity.

For historic context, when the Stone Saloon was initially built it was positioned along the original overland route running along the Mississippi river bluff between Saint Paul and the Fort Snelling Ferry. This unimproved but frequently trafficked route was known as the Old Fort Road. West 7th Street did not yet exist. By the close of Minnesota's Territorial Period, a number of businesses lined the Old Fort Road, including a large limestone livery stable along Old Fort Road near the city limits, a major brewery, and several saloons. The latter included Henry Shearn's Head Quarters Saloon on Leech Street near Ramsey Street; William Schimmel's saloon on Wilkin Street near the Saint Paul College; Alexander Erb's saloon and grocery at the corner of Smith (now Forbes) and Forbes (now Smith); John Fetzer's one-story home and lager beer saloon on Forbes (now Smith) immediately across the alley from the Stone Saloon to the north; and the Cave House Saloon just past the city limits near Richmond and Old Fort Road. All of these establishments have long since vanished. While perhaps not relevant to modern land use planning, the Stone Saloon is one of the last remaining vestiges of the Old Fort Road. As such, its restoration and proposed (re)use helps define the West 7th Street neighborhood's special identity, because it points to what came before. We take our historic assets where we find them—and if understood and used wisely, they have even greater value there.

Anthony Waldman House/Stone Saloon (1857) 2011 and 2015



(near bottom of High Bridge)



West 7th/Fort Road Federation 974 West 7th Street Saint Paul, Minnesota 55102

651-298-5599 FortRoadFederation.org

July 16, 2015

Barbara A. Wencl, Chair Saint Paul Planning Commission City Hall Conference Center, Room 40 15 Kellogg Boulevard West Saint Paul, MN 55102

Richard Dana, Chair Heritage Preservation Commission Planning and Economic Development 25 Fourth Street West, Suite 1400 Saint Paul MN 55102

Re: Anthony Waldman House a/k/a Stone Saloon, 445 Smith Ave N.

Dear Chairpersons Wencl and Dana:

At its July board meeting, the Board of Directors of the Fort Road Federation/District 9 Council listened to a detailed presentation of the proposed restoration and redevelopment of the historic Anthony Waldman House located at 445 Smith Avenue North, a/k/a the Stone Saloon.

As recently as 2008, this structure was a registered vacant building with several unaddressed nuisance and abatement orders. Nonetheless, the building is one of only a few surviving examples of vernacular-designed Pioneer Era limestone buildings in our neighborhood, and is perhaps the oldest-surviving commercial building in the city.

Fortunately, area resident Tom Schroeder purchased the building in mid-2008 and since then has invested considerable time, effort and money in researching, restoring and educating the public about this historic asset. Even in its partially-restored state, the building has attracted numerous media stories, tours and special events that have served to highlight the unique cultural and architectural history of our community, going back (as this building does) to the very origins of our statehood.

While the parcel on which the building sits is currently zoned residential, Tom has determined that the highest and best use of the building—and the use mostly likely to sustain the costly restoration and continued maintenance of the structure—is a return to its original historic use as a German-American "lager beer saloon." Under current licensing, the building would be used as a tap room, with brewery space, kitchen facilities, restrooms and utilities housed in a new addition to the rear of the historic structure. The positioning of the latter in new construction at the back

of the lot will help minimize any impacts on the integrity of the historic structures, without competing for their spotlight at the front of the lot.

We have reviewed the project site plan and proposed business use presented by Tom. The Board is unanimous in its support. Specifically:

- The Federation supports the local historic designation of the five, vernacular-designed limestone houses (including the Anthony Waldman House) now before the HPC and Planning Commission;
- The Federation supports the grant of a historic use variance to enable the Anthony Waldman House and surrounding site to be used as a tap room/brewery; and
- The Federation supports other zoning-related variances (such as set-back) enabling the construction of the brewery addition to the rear of the historic structures.

Thank you for your consideration of this important project.

Best Regards,

Shawn Devine

Chair, Fort Road Federation









HISTORIC SAINT PAUL

July 22, 2015

Barbara A. Wencl, Chair Saint Paul Planning Commission City Hall Conference Center, Room 40 15 Kellogg Boulevard West Saint Paul, MN 55102

Richard Dana, Chair
Heritage Preservation Commission
Planning and Economic Development
25 Fourth Street West, Suite 1400
Saint Paul MN 55102

Re: Anthony Waldman House a/k/a Stone Saloon, 445 Smith Ave N.

Dear Chairpersons Wencl and Dana:

We write to express our support for the local designation of the Pioneer Era Limestone Buildings of Saint Paul, and the continued redevelopment of the historic Anthony Waldman House located at 445 Smith Avenue, also known as the Stone Saloon.

Built in 1857, the Waldman House/Stone Saloon is a rare surviving example of vernacular-designed Pioneer Era limestone construction in the West 7th Street neighborhood. Tom Schroeder is proposing to return the Waldman House/Stone Saloon to its original historic use as a Civil War-era German "lager beer saloon," i.e., in modern terms, as a tap room/micro-brewery.

Historic Saint Paul's mission is to preserve and promote the cultural heritage, character, and vitality of Saint Paul neighborhoods. Tom presented his plans for the project and proposed business use to our Board at its July meeting, and several of our members have had the opportunity to visit the site. The Board supports this project.

As you may know, the proposed redevelopment of the Waldman House/Stone Saloon was a precipitating factor in the city's recent adoption of an historic use variance (HUV) ordinance. Other cities have used HUV ordinances to promote the successful redevelopment of historically designated structures, and we anticipate that future projects in Saint Paul will benefit from the ordinance.

We urge the HPC and Planning Commission to grant local historic designation to the Waldman House/Stone Saloon (together with the four other limestone buildings now before the HPC), as well as an historic use variance.

Thank you for your consideration.

Sincerely,

Tom Brock

President of the Board



June 29, 2015

Heritage Preservation Commission 25 W. Fourth Street, Suite 1400 Saint Paul, MN

Dear Board Members of the Heritage Preservation Commission,

I am writing to express support of Tom Schroeder's application for a Historic Use Variance for the Stone Saloon. Mr. Schroeder's rehabilitation efforts will revive the original character and purpose of the Stone Saloon, the oldest extant commercial building in St. Paul.

The Preservation Alliance of Minnesota is committed to promoting community assets and neighborhood engagement. A variety of citizens and local groups have offered their support and assistance to the Stone Saloon. On behalf of the Preservation Alliance of Minnesota, I am proud to add my support to this project.

Thank you for your consideration.

Sincerely,

Doug Gasek

Preservation Alliance of Minnesota, Executive Director

dgasek@mnpreservation.org









July 22, 2015

Dear St. Paul Heritage Preservation Commission, Planning Commission and City Council:

We are writing on behalf of the Little Bohemia Neighborhood Association (LBNA). The LBNA is a grassroots organization whose members are local residents, landlords, and business owners dedicated to developing a safe, clean, pedestrian-friendly, urban residential neighborhood.

We would like to support the grant of an 'historic use variance' so that the Stone Saloon can be (re)opened as a historic German lager beer saloon—i.e., a beer-only tap room and micro-brewery.

Through the LBNA's work with Invest Saint Paul / Neighborhood Stabilization Program and The Fort Road Federation we have worked to rehabilitate and resell some of the beautiful old homes in our neighborhood. Preserving and restoring old homes for their owners' enjoyment is great; preserving and restoring a historic, pre-Civil War German 'lager beer saloon' for the public to experience is fabulous!

As an organization we support local entrepreneurs who are willing to invest in the neighborhood, preserve and restore our old buildings, and contribute to a thriving West 7th community. The Stone Saloon will make a great gathering place for neighbors, friends, local organizations and history buffs.

The Little Bohemia Neighborhood Association supports the local designation of the Stone Saloon as a Heritage Preservation Site, so that it will be preserved for generations to come.

Best, Lindsay Kimball and Mark Fangmeier Co-Chairs, Little Bohemia Neighborhood Association TO: Amy Spong, Christine Boulware, Saint Paul HPC

FROM: Bob Frame, Historian DATE: August 21, 2014

RE: Structural engineer's evaluation of 445 Smith addition

I have read Richard (Rick) Johnson's structural evaluation of the wood-frame addition at 445 Smith on behalf of Tom Schroeder, with particular attention to the recommendations added in red. I also walked through the addition with Rick briefly, we discussed the findings he was preparing for the report, and he answered any questions I had. Listed below are the items that I find important in considering the possible repair, rehabilitation, and/or restoration of the structure. The report is limited to a structural evaluation by a registered engineer and does not attempt to be an architectural or historic evaluation. Nevertheless, as an engineer experienced with historic structures, he is aware of the fundamental requirement to preserve historic fabric and to repair rather than replace. From my perspective, this document provides a necessary baseline for determining the potential for repair or rehabilitation of the complete addition. Here are key points:

- Johnson concludes (section 8.B) that 20% of existing structural materials in the entire structure can be reused in their current structural configuration in any repair or rehabilitation effort. That percentage includes material of any age, some of which is not 50-year-old historic fabric.
- Most of the 20% is comprised of vertical wall studs, 70% of which can be reused in their existing structural configuration (7.E.1). This does not include the exterior wood board sheathing, which cannot be reused as structural material (7.E.2).
- Of the structural system for the two floors, only the second-floor joists can remain, but must be paired with new companion joists for adequate structural floor support (7.C.i, ii and appended sketch SK1). Like the exterior wood sheathing, the second-floor floorboards cannot be reused as structural material.
- No part of the main (first) floor system can be reused in a structural capacity, including the stone foundations, floor joists, and floorboards (7.D.i,ii,iii).
- The roof framing system cannot be reused, largely because of existing fire damage (7.A), but would not be structurally sufficient even if in sound condition.
- The interior stair cannot be reused structurally, or reconstructed in the same location without alterations to other parts of the structure (7.B).

This evaluation indicates that the addition, in its current structural condition, does not meet the State Building Code. At the same time, too much existing material—about 80%--must be replaced or be strengthened with additional new material for a repair to be feasible and prudent. Anything approximating a repair would essentially be new construction incorporating wall studs and some floor joists. Some existing material, or historic fabric, may be removed and salvaged, but its reuse would be in an aesthetic capacity and not necessarily in its original location or even in its original size and configuration.

If the structure cannot remain in its existing condition, and cannot feasibly be repaired using existing structural materials, the evaluation points to documentation and removal. The removal would be followed by new construction, if a replacement structure were desired. The approach to the design of a replacement structure would be a subsequent step, but consideration of an in-kind replacement to the extent possible would be the preferred approach to be in conformance with the Secretary of the Interior's Standards.

I'm happy to answer any questions (763-370-1803 or rframe@alumni.ksg.harvard.edu).

ALIGN Structural, Inc.

241 CLEVELAND AVENUE SOUTH SAINT PAUL, MINNESOTA 55105-1255 t 651.698.0164 | f 651.698.0165

Yust Architectural Services 476 West 7th Street Saint Paul, MN 55102 Attn: John Yust August 19, 2014

Re: 445 Smith Avenue-Structural Investigation

Saint Paul, MN Project #14246

Note: I have prepared this letter as a supplement to my original letter dated August 5, 2014. I have added recommendations for reinforcement or replacement of existing framing and foundation materials "in kind" to my original observations of the condition of the existing materials. These latest recommendations and comments are noted in red.

Background

At the request of Yust Architectural Services, I made a visit to the referenced building on August 4, 2014. The purpose of the visit was to perform limited visual observations of the existing framing and foundations of the structure. I have repared this letter to report my observations and to provide opinions regarding the existing structural materials in light of the current development of the site by Tom Schroeder.

Observations and Opinions

1. Roof

- A. Roof rafters were 1.875"x4" spaced at 25" on center
 - Members would be 64% overstressed in bending under residential loads per the latest edition of the Minnesota State Building Code (MSBC)
 - Members would be 74% overstressed in bending under commercial loads per the MSBC
 - Live and total load deflections under residential and commercial loads would not comply with the deflection limits per the MSBC
- B. Rafters were damaged by fire throughout the building, with the heaviest damage near the center and west ends of the space (Photo 1). The fire appeared to have caused a significant loss of cross section of many of the rafters and roof sheathing materials.
- C. Roof sheathing was .875" thick wood decking that was placed in various widths. The sheathing had randomly spaced gaps between the boards (Photo 1). There were conditions where the gaps between the sheathing boards were practically tight and there were conditions where I measured 1.5" wide gaps.
- D. There were gaps between the rafters at the roof peak that appeared to indicate spreading of the roof (outwards movement of the exterior stud walls). The gaps were more open at the base relative to the typically tight condition between the rafters at the top. This type of movement was much more severe

- at the rafters on the west end of the building. At this location the rafters and the exterior wall sheathing had completely separated exposing a gap that was approximately 1.75" wide (Photo 2).
- E. There was a noticeable deflection of the rafters. The deflection could be observed from the interior and exterior of the building. I confirmed the deflection with measurements of the slope of the rafters.
- F. The dormer along the south side of the roof did not appear to be original to the building. In addition, the following conditions at the dormer made it appear that there was little to no effort made to take care of the structural loads associated with this change to the original roof:
 - There was no lintel where the dormer was cut into the rafters
 - The full span rafters were not reinforced on either side of the dormer
 - There was no lintel above the window opening on the exterior wall at the dormer
- G. There were signs of moisture infiltration on the rafters and studs in many locations throughout the upper level.
- H. General structural condition of roof in light of proposed development of building:
 - i. The roof rafters were too badly damaged by fire and moisture infiltration to reuse the members for any proposed development of the structure. In addition, the members would require significant reinforcement to support loads per the MSBC.
 - ii. The current dormer condition would require significant structural reinforcement to support loads per the MSBC (for residential or commercial use of the building). There was almost a complete lack of any framing materials at this location and all structural elements to support the dormer would be new materials.
- I. Recommendations for reinforcement or replacement of existing roof structure in kind
 - i. The existing roof framing and sheathing materials would need to be removed due to the extent of the fire damage and cannot be reused.
 - ii. Option 1 for replacing the existing roof framing: Provide new wood roof trusses at 24" on center with new 5/8" thick plywood sheathing. Due to the raised ceiling condition there would need to be special consideration for resisting the horizontal forces at the truss bearing conditions along the tops of the exterior stud walls.
 - iii. Option 2 for replacing the existing roof framing:
 - Provide a new (3) 1.75"x18" LVL or W14x22 ridge beam- it should be noted that the span of the ridge beam would require relocation of the original chimney stack.
 - Provide new 2x8 rafters at 16" on center
 - iv. The dormer along the south side of the roof would require all new framing- framing along the perimeter of the roof penetration at the dormer would be (2) 1.75"x7.25" LVL beams

2. Stairs

- A. There was limited clearance at the top of the stairs
- B. The treads of the stairs were plywood which would not have been an original material in the building
- C. There did not appear to be a reasonable system of stair framing to properly transfer the stair loading to the main floor and foundation system below. Stair stringers were not evident and beams at the upper landing to support the stringer system were lacking.
- D. General structural condition of stairs in light of proposed development of building:
 - i. It does not appear that a workable stair configuration with proper clearances would be possible in the current stair location without a significant remodel of the existing roof structure above.
 - ii. A completely new framing system would be required to support stair loads per the MSBC.

- E. Recommendations for reinforcement or replacement of existing stair structure in kind
 - i. The existing stair framing would need to be removed due to the lack of a true structural system with a load path that transfers loads to the foundations. The existing framing members cannot be reused.
 - ii. The new stairs would require new stringers and treads/risers.
 - iii. The new stair would need to be relocated in the footprint of the building due to clearances at the head of the stair that are not code compliant, or the roof would need to be remodeled to provide proper clearances per the MSBC. If the roof is raised in this portion of the building, this would create snow drift conditions due to the new high/low roof framing planes.

3. Second Floor Framing

- A. Floor joists were 1.875"x5.75" spaced at 16" on center
 - Members would be 159% overstressed in bending under residential loads per the MSBC
 - Members would be 417% overstressed in bending under commercial loads per the MSBC
 - Members would be 94% overstressed in shear under commercial loads per the MSBC
 - Live and total load deflections under residential and commercial loads would not comply with the deflection limits per the MSBC
- B. General structural condition of the second floor in light of proposed development of building:

 The existing second floor joist framing system was so heavily overstressed that any reinforcement of the current system to support loads per the MSBC would essentially be a completely new system- the existing floor joists would provide an insignificant contribution to any "reinforced" framing scheme.
- C. Recommendations for reinforcement or replacement of existing second floor structure in kind
 - i. The existing 1.875"x5.75" floor joists at 16" on center would be reinforced with 1.75"x14" laminated veneer lumber (LVL) floor joists at 16" on center (or 1.75"x11.25" LVL joists at 16" on center for residential reuse of the building). Refer to Section 1/SK1 showing the new and existing joist relationship (Attached to this report).
 - ii. Installation of the new floor joists would interrupt the existing ledger system that is "let in" to the exterior wall studs to support the original second floor joists. Interrupting the existing ledger would necessitate adding fasteners from the existing floor joists into the existing wall stud.
 - iii. I would not recommend reusing the existing wood flooring at the second floor level. It would be difficult to estimate the capacity of the floor diaphragm to resist lateral loads on the building if the existing wood flooring was reused as the structural sheathing element at the second floor (the sheathing on the floor joists, roof rafters, and wall studs is the material that creates the diaphragm system to resist lateral loads on wood structures and carry forces through the building to the foundations).

4. Main Floor Framing and Foundations

- A. There were signs of moisture damage throughout the first floor level of the building that extended into the foundation materials. These signs included the following:
 - There were holes in walls where the structure had completely deteriorated (Photos 3 and 4).
 - The 8"x6" sills had deteriorated along much of the first floor perimeter (Photos 3 and 4). At some locations the wood had rotted to the point that a screwdriver could be easily inserted into the material that remained (Photo 4).

- It appeared that the heaviest amount of deterioration had occurred along the bases of the stud walls and at foundation conditions where the snow had been in contact with the structure throughout the winter months (Photos 4 and 5). This was especially true along the north wall of the building where maintaining the alley along that side of the building probably exacerbated the problem.
- Where stone foundation wall materials were accessible I was able to move some of the stone with my hand due to the deteriorated joint conditions. In addition, there were locations where large sections of the stone were missing. For instance, there appeared to be a section where 4" of stone had fallen away along the inside face of the foundation wall in the crawl space (Photo 6).
- There were floor joists that were badly deteriorated where they were bearing along the exterior stone foundation wall (Photo 7). No original wood materials would have been treated to resist the effects of exposure to moisture.
- B. John Yust (Architect) and Tom Schroeder (Owner) reported that they removed a great deal of silt from the crawl space below the main floor framing. I assumed that the stone foundation walls were porous enough to allow the silt to be brought in from the exterior.
- C. The main floor sheathing was buckled in some areas along the perimeter of the room where it appeared that the stone foundation materials below had moved upwards and caused distress to the sheathing. This type of distress was more significant along the north wall of the building (along the alley). I would suggest that water infiltration into the stone foundation wall had resulted in expansion of the wall during freezing temperatures. This theory is supported by the greater movement along the alley side of the building where snow would be added along the wall of the building during snow clearing efforts. This would contribute additional moisture along this wall of the building which would result in greater expansion during freeze events over time.
- D. The main floor joists were bearing on a 3.5"x3.5" wood beam that was supported by 3.5"x3.5" wood columns in the crawl space. The bases of the wood columns showed signs of exposure to moisture and it was not apparent what the posts were bearing on (Photo 8).
- E. General structural condition of main floor framing and foundations in light of proposed development of building:
 - i. Any floor joists with the type of deterioration observed at the bearing along the exterior stone foundation wall shown in Photo 7 would need to be removed and replaced.
 - ii. If any floor joists still have sound material where they bear along the exterior stone foundation wall, the foundation wall condition would need to be remodeled to support the joists in a manner that the joists would not be in contact with the stone material. The existing joists would not have been treated to resist contact with moisture at bearing conditions and this condition would need to be corrected. Remodeling the existing stone foundation wall would be difficult due to the relatively large width of the stone foundation wall along the perimeter of the building (17"-18" wide).
 - iii. The existing sill along the perimeter of the building would need to be removed and replaced due to the lack of preservative treatment in the existing members to resist the exposure to the moisture in the stone foundation walls. In addition, the deteriorated state of the existing sill would require removing most of this material anyways. Most of the sill conditions observed had deteriorated to the point that loads per the MSBC would not be properly transferred to the foundation system.
 - iv. The deteriorated joints and loose materials in the stone foundation walls make it extremely risky to reuse the walls with any redevelopment of the building. It would be difficult to simply grout

open joints in the walls due to the relatively massive width of the walls- it would not be possible to confirm that all open voids within the wall system were filled during the re-grouting efforts. Any open voids would continue to be susceptible to moisture infiltration in the future which could lead to expansion of the materials during freeze events. This is especially true along the existing alley where snow would continue to pile up during maintenance efforts and due to the fact that there is no moisture barrier along the exterior face of the foundation walls.

- F. Recommendations for reinforcement or replacement of existing main floor structure and foundations in kind
 - The columns supporting the center beam should be removed and cannot be reused. To provide a more efficient structural system, two new 4x4 wood posts would be used to support (2) 1.75"x9.5" LVL beams (currently there are four or five interior columns along the center beam line). These columns would bear on concrete footings that would be 2'-6"x2'-6"x12" thick with 4-#4 reinforcing bars each way at the bottom of the footing.
 - ii. The main floor joists would be replaced with 2x10 floor joists spaced at 16" on center. The existing floor joists were deteriorated and cannot be reused as part of the main floor structural system.
 - iii. The stone foundation walls would be removed and replaced with the following:
 - 24"x12" thick continuous concrete footing with 2-#5 continuous reinforcing bars
 - Footing to bear at least 3'-6" below the adjacent finish grade
 - Provide a 12" foundation wall made up of concrete masonry units (CMU). CMU would be reinforced with #5 reinforcing bars placed at 48" on center. The top course of the CMU would be a bond beam with 2-#4 continuous reinforcing bars. A limestone veneer could be included where the foundation wall is exposed above grade.

I would recommend against using a full stone foundation wall system as the material would be susceptible to water infiltration and the unreinforced stone would not be appropriate to resist lateral loads from the adjacent backfill material (Also refer to Section 4.E.iv of this report for further discussion of this topic).

- iv. The existing sill plate at the base of the stud walls would need to be replaced with a continuous treated sill plate. The existing sill plate cannot be reused.
- v. I would not recommend reusing the existing wood flooring at the main floor level. Similar to the recommendations for the second floor level, reusing the existing wood flooring would not provide a reliable diaphragm to resist lateral loads on the structure (Refer to Item 3.C.iii of this report).

5. One Story Shed on West Side of Building

- A. The one story shed on the west side of the building was not constructed along with the original structure.
- B. The wood rafters and wall studs showed signs of moisture infiltration throughout the addition.
- C. It was unclear if there was a foundation system along the exterior stud wall of the shed that extended to frost depth or to the bedrock below. The concrete below the stud wall was cracked and appeared to have undergone excessively differential movement along the length of the wall (Photo 9)
- D. General structural condition of shed in light of proposed development of building:
 - The existing framing materials at the one story shed have been exposed to so much moisture over the years I would recommend against reuse of the materials for any development of the building.

ii. There were no signs of a true foundation system supporting the stud walls of the one story shed. A new foundation system would be required for any structure in this location.

6. Exterior Wall Studs

- A. The existing wall studs showed signs of moisture infiltration at many locations throughout the building.
- B. The existing studs had deteriorated due to moisture infiltration along the base of the walls (Photos 3 and 4).
- C. Recommendations for reinforcement or replacement of existing wall studs in kind
 - i. Existing studs that had been damaged by moisture cannot be reused.
 - ii. The existing studs that had been sistered to the original studs along the east gable end of the building during the past remodeling of the original structure should be removed and replaced (Photo 10). This existing condition is not structurally acceptable.

7. Quantitative Analysis of Reuse of Existing Materials for Repair of the Building

- A. Roof framing- 0% of the existing structural materials from the roof level can be reused for the proposed development of the building. The existing materials were damaged by fire and cannot be reused.
- B. Stair framing- 0% of the existing structural materials at the stairs can be reused. The existing framing system does not provide a continuous load path to the foundations.

C. Second floor framing

- i. 0% of the existing flooring can be reused for development of the building. The existing boards do not create a proper structural diaphragm to transfer lateral loads (wind loads) through the building to the foundations.
- ii. All of the existing floor joists could potentially remain in place. However, the new floor framing materials required to reinforce the existing system to resist loads per the MSBC would carry a significant majority of the loads. The bending moment capacity of the new LVL joists is 10 times greater than the bending moment capacity of the existing joists. In other words, the existing floor joists would no longer function as such because they would have an insignificant contribution to the actual structural performance of the building.

D. Main floor framing and foundations

- 0% of the existing foundations can be reused for the development of the building. The materials
 have deteriorated and the ungrouted condition will continue to allow water infiltration.

 Allowing water infiltration will leave the building vulnerable to future damage due to trapped
 moisture creating overstress conditions during freeze-thaw cycles.
- ii. 0% of the main floor joists can be reused. The joists have been damaged due to moisture infiltration to the point that they would not perform structurally and they should not be in contact with the new framing materials.
- iii. 0% of the existing wood flooring can be reused. Like the recommendations for the second floor level, the reuse of the existing flooring would not create a proper structural diaphragm to act as part of the lateral load resisting system.

E. Wall studs

- i. I would estimate that 70% of the wall studs can be reused. The other 30% of the studs have been damaged by moisture and cannot be reused.
- ii. 0% of the existing wood boards on the outside face of the studs can be reused. As with the existing wood boards on the floor framing, the existing boards will not provide a diaphragm to resist lateral loads on the building.

8. Practical Concerns Regarding Construction of "In Kind" Structure

- A. Based on my observations, the only structural materials that would be reused for the proposed development of the building would be the second level floor joists and any wall studs that have not been damaged by moisture. However, the existing second floor joists would not be a functioning part of the structural system (Refer to Item 7.C.ii of this report). To accomplish the preservation of the second floor joists and the sound wall studs, a temporary shoring system would need to be installed to suspend the building while the new footings, foundation walls, and framing are constructed. The supports for the shoring system would need to be located far enough outside the building footprint to allow excavation and construction of the new footings and foundation walls as they are built up to the underside of the existing studs that will be suspended in space.
- B. I estimate that 20% of the existing structural materials would be reused for the restoration of the building.

Additional Comments

- 1. The opinions and conclusions expressed in this report are based on the reviewed information, site observations, and observations of the artifacts as well as my training, education, and experience. These opinions and conclusions are held to a reasonable degree of certainty. As additional information becomes available, I reserve the right to update or supplement the report.
- 2. It shall be noted that our firm has not been engaged to provide structural design and/or detailing of shoring required to temporarily support any framing or foundation materials that have been overstressed and will need to be repaired or replaced.
- 3. This report shall not be considered a construction document for performing any remedial work on the structural systems mentioned herein. All remedial structural work shall be completed in accordance with the provisions of the Minnesota State Building Code.

Please contact our office with any questions or comments regarding the structural conditions for the project.

Respectfully Submitted,

Richard W. Johnson, PE, Senior Project Engineer

Minnesota Registration #23406




Photo 1- Fire damage at roof level



Photo 2- Gap between rafters and wall sheathing on west end of roof



Photo 3- Openings in exterior stud wall



Photo 4- Rotted wood and deteriorated stone materials at base of stud wall



Photo 5- Rotted wood and missing/deteriorated stone materials at base of stud wall



Photo 6- Looking downwards at a section of stone that had deteriorated along the foundation wall



Photo 7- Deteriorated joists and sill at bearing on stone foundation wall



Photo 8- Signs of moisture on columns in crawl space



Photo 9- Signs of movement in concrete supporting stud walls of one story shed on west side of building




Photo 10- Sistered wall studs along east gable end at previous remodeling efforts

ALIGN Structural, Inc.

241 Cleveland Avenue South, Suite B7 Saint Paul, Minnesota 55105

PROJECT 445 SMITH AVENUE	JOB NO	14246	ATE 8-19-14
JECT STRUCTURAL INVESTIGATION	BY RWJ	SHEET NO. SK	1 of 1







414 7th St. W. St. Paul, MN 55102

To Whom It May Concern,

Bad Weather Brewing Company and the Stone Saloon share an alleyway with private residences. The nature of our businesses requires use of the alleyway for deliveries, pickups and waste services. We are lucky enough to have a large alleyway to easily accommodate both our business without a problem, however we want to do everything we can to be respectful to our neighbors utilizing the alleyway.

Our businesses have a large overlap with regard to supplies we will order. Bad Weather Brewing and the Stone Saloon plan to work together on ordering ingredients and supplies, meaning we can share deliveries and minimize truck traffic through the alleyway. We are also outlining a plan for shared waste disposal and recycling which will also minimize truck traffic.

Continuing to work with the Stone Saloon and our surrounding neighbors is extremely important to us, and helps foster a safe and happy community for all businesses and residents. Our intent with this letter is to show Bad Weather Brewing and Stone Saloon will be committed and respectful neighbors to everyone in our community.

Sincerely,

Zac Carpenter and Joe Giambruno

Founders - Bad Weather Brewing Company







