



Building Entrance



Entrance detail under overhang



Existing roof drain



Ash Trees along sidewalk



View of play area from St. Clair Ave.



Building and sidewalk condition



Building lighting



Existing field access between trees



Existing site furnishings



Existing 2 - 5 Play Area



Existing 5 - 12 Play Area



Sunken sidewalk at low point



Uneven sidewalk at entrance



Uneven sidewalk by play area

St. Clair Play Area Renovation

October 13, 2009

Existing Conditions

