CITY OF SAINT PAUL HERITAGE PRESERVATION COMMISSION STAFF REPORT

FILE NAME: 400 Summit Avenue

DATE OF APPLICATION: May 22, 2014

APPLICANT: Bryan Horton, Renewal by Andersen

OWNER: Robert Rulon Miller

DATE OF PUBLIC HEARING: August 28, 2014

HPC SITE/DISTRICT: Historic Hill District

CATEGORY: Pivotal

CLASSIFICATION: Building permit

STAFF INVESTIGATION AND REPORT: Christine Boulware, John Beaty

DATE: August 20, 2014

A. SITE DESCRIPTION: The Maurice Auerback House is a three-story residence constructed in 1882 in the Queen Anne style. In 1891 alterations were made to extend the walls on the west and south sides. In the 1920s the facade was altered and the residence was remodeled to the present villa style appearance. The green tile roof has a truncated hip with truncated hipped wings extending to the left (east) and the right rear. Each section has a front-facing, arched closed pediment dormer and there two interior rendered (stuccoed) chimneys. The exterior is also rendered, with raised keystones, jack arches, and quoins. The entry door has an arched transom and a surround with twinned square Doric pilasters supporting a full entablature with a balustrade above.

The fenestration consists of an irregular facade composition with paired, tall, double-hung windows and a large, arched, stairway window without a surround to the east of the entry. All windows are one -over-one double-hungs with the exception of the window onto the servant stair landing on the front elevation, which has two Queen Anne style geometrically-divided sashes, the large arched window at the main stair landing, and the six-over-six, double-hung windows in the dormers. On the east side of the residence there is a projecting porch with a balustrade above and the property has a tiled, hiproofed garage.

B. PROPOSED CHANGES: The applicant proposes to replace seven windows in the building with one-over-one double-hung windows; including the Queen Anne style window which remains from the 1882 construction. Window screens were not specified in the application.

C. BACKGROUND

June 10, 2014 – Staff sent an email to Mr. Horton to inform him that the stairway window should be repaired due to the sash pattern and condition.

June 19, 2014 – Second email from staff to Mr. Horton informing Mr. Horton that based on the guide-lines; the divided light window should be repaired or replaced to match the existing window.

Mr. Horton responded to staff's email in which noted understanding of the guidelines citing replacement in-kind and discussed the desire of the owner to replace the stairway window to match the other new windows on the property.

Staff responded and informed Mr. Horton of the two options for the applications: for staff to continue reviewing the application with more detailed information on the residence, or schedule the application for a public hearing. Staff noted that based on the current application staff cannot approve the divided light wood window with a replacement window that does not have divided lights to match.

July 9, 2014 – Staff spoke with Kim Tobin of Renewal by Andersen on the phone. Ms. Tobin encouraged staff to approve the replacement of the stairway window to have no lights based on Renewal by

Andersen's past window replacement at the residence which consisted of replacement of one-over-one double-hung windows with matching style and configuration.

July 29, 2014 – Staff received an email from Ms. Tobin requesting that the proposal to replace the divided-light window with a clear glass window be reconsidered.

Staff responded to Ms. Tobin's email explaining that staff can only approve window repair or window replacement to match the existing or historic windows. Staff cited the Design Review Guidelines for Windows and Doors and informed that the application, as is, would require review by the Heritage Preservation Commission.

August 12, 2014 – Staff confirmed with Mr. Horton that the application as submitted would be reviewed by the HPC at the August 28 public hearing. Mr. Horton indicated that he would not be present, but the property owner would attend to represent the application.

August 14, 2014 – Staff conducted a site visit to observe and photograph the windows proposed for replacement. Staff advised the homeowner that the Queen Anne style window is in a condition that can be retained and repaired and offered to provide a list of several local companies that repair historic windows.

D. GUIDELINE CITATIONS:

SECRETARY OF THE INTERIOR STANDARDS FOR REHABILITATION

- 1. A property shall be used for its historic purpose or be placed in a new use that requires minimal change to the defining characteristics of the building and its site and environment.
- 2. The historic character of a property shall be retained and preserved. The removal of historic materials or alteration of features and spaces that characterize a property shall be avoided.
- 3. Each property shall be recognized as a physical record of its time, place, and use. Changes that create a false sense of historical development, such as adding conjectural features or architectural elements from other buildings, shall not be undertaken.
- 4. Most properties change over time; those changes that have acquired historic significance in their own right shall be retained and preserved.
- 5. Distinctive features, finishes, and construction techniques or examples of craftsmanship that characterize a historic property shall be preserved.
- 6. Deteriorated historic features shall be repaired rather than replaced. Where the severity of deterioration requires replacement of a distinctive feature, the new feature shall match the old in design, color, texture, and other visual qualities and, where possible, materials. Replacement of missing features shall be substantiated by documentary, physical, or pictorial evidence.
- 7. Chemical or physical treatments, such as sandblasting, that cause damage to historic materials shall not be used. The surface cleaning of structures, if appropriate, shall be undertaken using the gentlest means possible.
- 8. Significant archeological resources affected by a project shall be protected and preserved. If such resources must be disturbed, mitigation measures shall be undertaken.
- 9. New additions, exterior alterations, or related new construction shall not destroy historic materials that characterize the property. The new work shall be differentiated from the old and shall be compatible with the massing, size, scale, and architectural features to protect the historic integrity of the property and its environment.
- 10. New additions and adjacent or related new construction shall be undertaken in such a manner that if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

Historic Hill District Design Review Guidelines

Sec. 74.64. - Restoration and rehabilitation.

(a) General Principles:

- 1. Every reasonable effort shall be made to provide a compatible use for a property which requires minimal alteration of the building, structure, or site and its environment, or to use a property for its originally intended purpose.
- 2. The distinguishing original qualities or character of a building, structure, or site and its environment shall not be destroyed. The removal or alteration of any historic material or distinctive architectural features should be avoided when possible.
- 3. All buildings, structures, and sites shall be recognized as products of their own time. Alterations that have no historical basis and which seek to create an earlier appearance shall be discouraged.
- 4. Changes which may have taken place in the course of time are evidence of the history and development of a building, structure, or site and its environment. Theses changes may have acquired significance in their own right, and this significance shall be recognized and respected.
- 5. Distinctive stylistic features or examples of skilled craftsmanship which characterize a building, structure, or site shall be treated with sensitivity.
- 6. Deteriorated architectural features shall be repaired rather than replaced, whenever possible. In the event replacement is necessary, the new material should match the material being replaced in composition, design, color, texture, and other visual qualities. Repair or replacement of missing architectural features should be based on accurate duplications of features, substantiated by historic, physical, or pictorial evidence rather than on conjectural designs or the availability of different architectural elements from other buildings or structures.
- 7. The surface cleaning of structures shall be undertaken with the gentlest means possible. Sandblasting and other cleaning methods that will damage the historic building materials shall not be undertaken.
- 8. Every reasonable effort shall be made to protect and preserve archaeological resources affected by, or adjacent to any project.
- 9. Contemporary design for alterations and additions to existing properties shall not be discouraged when such alterations and additions do not destroy significant historical, architectural or cultural material, and such design is compatible with the size, scale, color, material, and character of the property, neighborhood, or environment.
- 10. Wherever possible, new additions or alterations to structures shall be done in such a manner that if such alterations were to be removed in the future, the essential form and integrity of the structure would be unimpaired.

(e) Windows and Doors:

- (1) Existing window and door openings should be retained. New window and door openings should not be introduced into principal elevations. Enlarging or reducing window or door openings to fit stock window sash or new stock door sizes should not be done. The size of window panes or sash should not be altered. Such changes destroy the scale and proportion of the building.
- (2) Window sash, glass, lintels, sills, architraves, doors, pediments, hoods, steps and all hardware should be retained. Discarding original doors and door hardware, when they can be repaired and reused in place, should be avoided.
- (3) The stylistic period(s) a building represents should be respected. If replacement of window sash or doors is necessary, the replacement should duplicate the material, design and hardware of the older window sash or door. Inappropriate new window and door features such as aluminum storm and screen window combinations, plastic or metal strip awnings, or fake shutters that disturb the character and appearance of the building should not be used. Combination storm windows should have wood frames or be painted to match trim colors.

E. FINDINGS:

- 1. On April 2, 1991, the most recent expansion of the Historic Hill Heritage Preservation District was established under Ordinance No. 17815, § 3(II), reflecting today's boundaries. The Heritage Preservation Commission shall protect the architectural character of heritage preservation sites through review and approval or denial of applications for city permits for exterior work within designated heritage preservation sites §73.04.(4).
- **2.** The property at 400 Summit Avenue is categorized as pivotal to the character of the Historic Hill Heritage Preservation District.
- 3. The proposal to replace existing one-over-one double-hung windows on the side and rear elevations with new one-over-one double-hung windows with similar-sized rails and stiles generally conforms to the guidelines for the district (Sec. 74.64(e)(3)).
- **4.** The proposal to replace a double hung window with geometrically-divided Queen Anne sash on the principle (front) elevation with a one-over-one window does not comply with the guidelines for the District (Sec. 74.64(e)(3)) as the replacement does not duplicate the design of the original sash.
- **5.** Screens were not included in the application but will need to be installed in the openings, as historically: full-frame, flush-mount, with horizontal bar that lines up with the window meeting rail.
- **6.** The proposal to replace the divided-light window with a window with undivided sashes at the Maurice Auerback House will adversely affect the Program for the Preservation and architectural control of the Historic Hill Heritage Preservation District (Leg. Code §73.06 (e)). The replacement of one-over-one windows with new one-over-windows in a similar style will not adversely affect the Program for Preservation.

F. STAFF RECOMMENDATIONS:

Based on the findings staff recommends partial approval of the building permit application provided the following condition(s) are met:

- **1.** The one-over-one, double-hung windows on the side and rear elevations may be replaced to match the existing in size, profile, style and detail.
- **2.** The original Queen Anne style divided-light window on the front elevation shall be retained and repaired.
- 3. New windows approved for installation at the property shall have full-frame, flush-mount screens historically accurate profiles and a horizontal bar that lines up with the meeting rail installed that the same plane as the historic screen/storm windows.
- **4.** There shall be no wrapping or paining of the window trim or sills.
- **5.** All final materials, details and colors shall be reviewed and approved by HPC staff or the HPC.
- **6.** Any revisions to the approved plans must be submitted to the HPC and/or staff for review.

G. ATTACHMENTS

- 1. HPC application and submittals
- 2. Historic information and photographs
- 3. Staff photographs August 14, 2014
- 4. List of previous window replacements at 400 Summit Ave.



Saint Paul Heritage Preservation Commission Department of Planning and Economic Development 25 Fourth Street West, Suite 1400 Saint Paul, MN 55102

Phone: (651) 266-9078

HERITAGE PRESERVATION COMMISSION DESIGN REVIEW APPLICATION

This application must be completed in addition to the appropriate city permit application if the affected property is an individually designated landmark or located within an historic district. For applications that must be reviewed by the Heritage Preservation Commission refer to the HPC Meeting schedule for meeting dates and deadlines.

1.	CATEGORY		
Plea	ase check the category th	at best describes the propose	d work
Re □ M □ De	epair/Rehabilitation oving emolition	☐ Sign/Awning ☐ Fence/Retaining Wall ☐ Other	☐ New Construction/Addition/ Alteration ☐ Pre-Application Review Only
2.	PROJECT ADDRESS		
Stre	eet and number:	Summit Avenue	Zip Code: _ <i>55/02</i>
3.	APPLICANT INFORM	IATION	
		•	C West
City	y: Roseville	State:	Zip Code: <u>55//3</u>
			yan horton@andersencorp. c
4.	PROPERTY OWNER(S) INFORMATION (If diffe	rent from applicant)
Nan	ne: <u>Robert</u> Ru	Von-Miller	
Stre	eet and number:400	Summit Ave	
City	: St. Paul	State:	Zip Code: <u>55102</u>
Pho	one number: (65/) 29	<i>0-0700</i> e-mail:	N/A

	applicable)	resources Affiliation and the second	
Contact person:			
Company:			
Street and number:			
City:	State:	Zip Code:	
Phone number: ()	e-mail:		
6. PROJECT DESCRIPTION			
foundation or porches. Attach features, if applicable, including co	specifications for do olor and material samp		1
Proposing to (cplace 7 wind width/Height replacements.	HOWS Within the R. 1911 Equal Sash ra	xisting openings. Custom tio Double Hung. Terratoru ioled, All Exterior Storms remove	
Exterior & White Interior (olor samples provi	iole d) All Exterior Storms remove	-/
			4
STAIDWAY- Course care las	1 lavia - Home Will	he fixed Current Prairie	1
STAIDWAY- Course care las	1 lavia - Home Will	he fixed Current Prairie	1
STAIDWAY- Course care las	1 lavia - Home Will	he fixed Current Prairie	1
STAIDHIAN-COURSE COCI LAC	1 lavia - Home Will	he fixed Current Prairie	1
STAIDWAY- Course care las	1 lavia - Home Will	he fixed Current Prairie	1
STAIRWAY-Server Sash/frame grille style, NO grille on ne laundry-server sash damag Hallway-doesn't operate, serve Master bldroom- All in opera This will be the 3td replace papetwork will show bet	1 lavia - Home Will	he fixed Current Prairie	1
STAIDWAY- Course care las	1 lavia - Home Will	be fixed. Current Prairie facing (Blocked by landscaping) sash missing. No grille - a m-East facing for this property. The enclosed examples from previous Attach additional sheets if necessary	1
STAIRWAY-Server Sash/frame grille style, NO grille on ne laundry-server sash damag Hallway-doesn't operate, serve Master bldroom- All in opera This will be the 3td replace papetwork will show bet	1 lavia - Home Will	the fixed. Current Prairie A facing (Blocked by landscaping) In sash missing. No grille - a In-East facing By this property. The enclosed examples from previous	1
STAIRWAY-Server Sash/frame grille Style, NO grille on ne Laundry-Severe Sash damag Hallway-doesn't operate, serve Master bedroom-All in opera This will be the 3 rd replace paperwork will show be t abl's project. 7. ATTACHMENTS Refer to the Design Review H	de kerioration with the proposed. North e, glass in bottom wely damaged Storm blu South facing ment proposal to fore and after h	the fixed. Current Prairie of facing (Blocked by landscaping) of sash missing. No grille - a on - East facing of this property. The enclosed examples from previous Attach additional sheets if necessary	1
STAIRWAY-Server Sash / frame grille Style, NO grille on ne Laundry-Severe Sash damag Hallway-doesn't operate, serve Master bedroom-All in opera This will be the 3 ^{cd} replace paperwork will show be t abl's project. 7. ATTACHMENTS Refer to the Design Review F **INCOMPLETE A	de kerioration William proposed. North e, glass in bottom rely damaged Storm ble South facing ment proposal to fore and after a Process sheet for require	the fixed. Current Prairie of facing (Blocked by landscaping) of sash missing. No grille - a on - East facing of this property. The enclosed examples from previous Attach additional sheets if necessary	1
STAIRWAY-Server Sash / frame grille Style, NO grille on ne Laundry-Severe Sash damag Hallway-doesn't operate, serve Master bedroom-All in opera This will be the 3 ^{cd} replace paperwork will show be t abl's project. 7. ATTACHMENTS Refer to the Design Review F **INCOMPLETE A	de kerioration William proposed. North e, glass in bottom rely damaged Storm ble South facing ment proposal to fore and after a Process sheet for require	the fixed. Current Prairie A facing (Blocked by landscaping) In sash missing. No grille - a In - East facing Con + this property. The enclosed examples from previous Attach additional sheets if necessary d information or attachments. L BE RETURNED**	1

District:/Individual Site: Contributing/Non-contributing/Pivotal/Supportive/: Type of work: Minor/Moderate/Major Requires staff review	ge Preservation Commission. A		
Date received:	Date:		
Date received: 5 · 22 · 14 District:/Individual Site: Contributing/Non-contributing/Pivotal/Supportive/: Type of work: Minor/Moderate/Major Requires staff review			
Date received: 5 · 22 · 14 District:/Individual Site: Contributing/Non-contributing/Pivotal/Supportive/: Type of work: Minor/Moderate/Major Requires staff review			
District:/Individual Site: Contributing/Non-contributing/Pivotal/Supportive/: Type of work: Minor/Moderate/Major Requires staff review Requires staff review Requires staff review Supporting data: YES NO Complete application: YES NO The following condition(s) must be met in order for application to conform to preservation program: Ci Ci Ci Hearing I It has been determined that the work to be performed pursuant to the application does not adversely affect the program for preservation and architectural control of the	LY		
Contributing/Non-contributing/Pivotal/Supportive/: Type of work: Minor/Moderate/Major Requires staff review Supporting data: YES NO Complete application: YES NO The following condition(s) must be met in order for application to conform to preservation program: It has been determined that the work to be performed pursuant to the application does not adversely affect the program for preservation and architectural control of the	ILE NO.		
Supporting data: YES NO Complete application: YES NO The following condition(s) must be met in order for application to conform to preservation program: It has been determined that the work to be performed pursuant to the application does not adversely affect the program for preservation and architectural control of the			
Complete application: YES NO The following condition(s) must be met in order for application to conform to preservation program: It has been determined that the work to be performed pursuant to the application does not adversely affect the program for preservation and architectural control of the	res Commission review		
It has been determined that the work to be performed pursuant to the application does not adversely affect the program for preservation and architectural control of the	Sets of Plans Sets of Plans reduced to 2" by 11" or 11" by 17" otographs y Permit Application mplete HPC Design Review blication		
work to be performed pursuant to the application does not adversely affect the program for preservation and architectural control of the	ate set for:		
heritage preservation district or site (Ch.73.06).	it#		
HPC staff approval	It II		


400 Summit Avenue

Renewal by Andersen


Window Replacement

Submitted by: Bryan Horton











Hallway Window






Bathroom Window





Laundry Window





Laundry Window Detail







Sash Rail deterioration

Bottom sash out of frame, glass missing


Master Bedroom Windows (3) Interior




Master Bedroom Window Exterior



Before and After Example Exterior







Auerback House, 1882



Auerback House, 1977



Auerback House, façade



Auerback House, east elevation



Auerback House, south elevation



Auerback House, south elevation



Auerback House, stair window interior detail

List of previous window replacements at 400 Summit Avenue by Renewal by Anderson

Date	File #	Proposed	Conditions
05/31/2012	12-062970	Replace 12 windows on all four elevations	New windows shall match old. Flush mount screens with horizontal bar shall be added
11/04/2005	05-187372 06-073	Replace 7 (5 units) windows on front and west elevation	
11/14/2001	01-235639 B02-063	Replace 3 windows on front and west elevation	n/a