

Update signage. Discuss placement of Eileen Weida Memorial stone.



Topography within the park provides interest and a unique play experiences.



Protect mature elm. Keep construction minimal around the dripline, prune to raise branches.



Majority of concrete is in good condition. Salvage where appropriate.



Replace play sand with modern materials such as soft playground tiles or synthetic poured in place



Replace outdated and worn out play equipment.



Provide updated furnishings such as benches, fencing, bike racks, trash receptacles, and picnic tables.



Improve lighting around the play area by replacing burnt out bulbs and pruning branches for more clearance



Granite stage under the elm tree remains in good condition



Eileen Weida Play Area

637 Burr Street, Saint Paul, MN 55130

site analysis

