

EXISTING CONDITIONS



1 View towards the back of the recreation center building- there are no windows that face onto the existing play area.



2 View of the rear access to the recreation center- the most direct connection from the building to the existing play area.




3 A view of the basketball half court and the eastern wall of the rec center beyond showing the large blank facade.



4 View of the existing play area showing the unique play elements. A view of the rear facade of the library is in the background showing how this area is obscured and hidden from sightlines.



5 A view of the classroom window and director's office window that faces south onto a flat open lawn space.



CONWAY RECREATION CENTER EXISTING CONDITIONS



6 A view of the play elements and the gently rolling topography and mature trees beyond.



7 East entrance to the Conway recreation center.



8 Existing basketball half court and bang board in the background.



9 Existing play equipment is built into a large earthmound and uses ramps and retaining wall to create a unique play area.



10 Play surface is deteriorating and presents a safety hazard for play area users.



11 Play equipment is in need of repair and/or replacement due to age, condition, and safety hazards.



12 Existing play equipment is not usable due to the age or condition.



13 Existing play area equipment for ages 2-5

CONWAY PLAY AREA RENOVATION

SAINT PAUL, MINNESOTA

introductory meeting
March 3, 2011

