



**1. East Shore Dr./Frost Ave. Intersection**

- Hidden Intersection
- No park identification at north end of Park

**2. Intersection at north end of Lake Phalen**

- Sharp bend in road
- Bad intersection with park road



**3. Parking lot/Boat Ramp**

- Over abundance of paving
- Confusing circulation
- Boat ramp crosses trails



**4. East Shore Drive**

- Narrow, shared trails
- No room for tree planting
- Creates pedestrian and bicycle congestion

**5. Entrance from Arcade**

- Only northbound vehicles can enter park
- No exit to Arcade
- One way southbound street



**6. Dead end on Phalen Drive**

- Circulation for north bound vehicles ends abruptly at one-way from the north



**7. Parking lot access**

- Southbound vehicles are prohibited from turning left into parking lots on Phalen Drive

**8. Arcade & Wheellock Parkway Intersection**

- Multiple intersecting streets create a confusing intersection
- Unclear bike/pedestrian crossing

**9. Larpenteur and Arlington Avenue intersections**

- Stop signs on East Shore Drive at Larpenteur and Arlington Avenues frequently become overlooked

**10. Wheellock Parkway**

- Nice parkway appearance with center median
- No boulevard planting in some locations

**11. South Parking Lot**

- Parking lot at south end of Lake Phalen undersized
- Exit is hidden behind corner and evergreen trees
- Parking area creates narrow area where congestion occurs with pedestrians and bicyclists

**12. Maryland Avenue and Johnson Parkway**

- Very busy intersection
- No controlled left hand turns