

# METRO Gold Line BRT Project

St. Paul Heritage Preservation Commission

July 26, 2021





# Today's Presentation

- Gold Line Section 106 Recap
- Assessment of Effects for historic properties in St. Paul 60% Plans
- Next Steps



# Gold Line Section 106 Recap



## Section 106

#### Federal process to evaluate project effects to historic properties

- Federal Transit Administration is the lead federal agency
- Requires identification and survey of historic properties
- Assessment of effects may result in no effect, no adverse effect, or an adverse effect
- Consultation is the process to consider measures to avoid, minimize, and/or mitigate any adverse effects
  - State Historic Preservation Office (SHPO)
  - Heritage Preservation Commissions (HPCs)
  - Other parties with interest in Project effects on historic properties
  - Public

## Assessment and Design Review Recap

- Assessment of Effects Report (30% Plans)
  - FTA made No Adverse Effect with Conditions Finding November 2020
  - St. Paul HPC Meeting February 2021
  - Consulting party comments received March 2021
- Assessment of Effects Report Addendum (60% Plans)
  - FTA made No Adverse Effect with Conditions Finding June 2021 <u>https://www.metrotransit.org/Data/Sites/1/media/about/improvements/gol</u> <u>d-line/gtwy brt determination of effects 60-pct-addendum final.pdf</u>
  - Consulting party comments due by August 2, 2021



## Assessment of Effects - 60% Plans



## Assessment of Effects - 60% Plans


- The 60% plans were reviewed for:
  - Substantive changes
  - Sufficient detail to address the conditions applied to select historic properties
- Consultation on historic properties with revised findings since 30% Assessment of Effects
- Presentation will focus on St. Paul properties with No Adverse Effect and No Adverse Effect with conditions

## Properties with Revised Findings (St. Paul)


- Johnson Parkway
- Texas Company Service Station
- Lowertown Historic District
- Urban Renewal Historic District

- Pioneer Endicott / Endicott Arcade Addition
- Manhattan Building
- Landmark Center
- Rice Park Historic District
- Hamm Building


### Properties with Revised Findings (St. Paul)



## Johnson Parkway, Saint Paul



# Location: West of Etna Street Station





Johnson Parkway: No Adverse Effect

## Johnson Parkway, Saint Paul - 60% Plans



## Johnson Parkway, Saint Paul - 60% Finding

#### **No Adverse Effect**

• The conditions from the findings based on 30% design are no longer necessary.


### Texas Company Service Station, Saint Paul

#### Location: West of Maple Street pedestrian bridge



Texas Company Service Station: No Adverse Effect with updated condition

### Texaco Service Station - 60% Plans




## Texaco Service Station - 60% Finding


#### No Adverse Effect with the following condition

 Construction documents (plans and specifications) are reviewed at each of the remaining design stages (90%, 100%, and any changes made to the 100% plans) to ensure that alternative construction methods recommended to reduce potential for construction-related damage are incorporated.

## Sibley and Wacouta Station Area



#### Location: Downtown at Sibley Street and Wacouta Street




Lowertown Historic District: No Adverse Effect with updated conditions



# Shelter Type 1 - 60% Plans


- Union Depot/Wacouta Street Union Depot/Sibley Street Stations
- Reduced size. Side Platform: 34'8" long and 10'8" wide. Canopy: 47' long, 10'7" wide, and 13'8" tall








# Shelter Type 1 - 60% Plans



## Lowertown Historic District - 60% Plans




### Lowertown Historic District - 60% Findings

#### No Adverse Effect with the following conditions

- Construction documents (plans and specifications) are reviewed at each of the remaining design stages (90%, 100%, and any changes made to the 100% plans) to ensure that alternative construction methods recommended to reduce potential for construction-related damage are incorporated.
- Shelter finishes are reviewed with consulting parties at the 90% design stage to ensure they meet the SOI Standards.

# 5<sup>th</sup> Street / Robert Street Station Area




#### Location: 5<sup>th</sup> and Robert Street



#### Urban Renewal Historic District: No Adverse Effect with updated conditions



# 5<sup>th</sup> Street / Robert Street Station Area




Manhattan Building, Pioneer Press and Endicott Buildings, and Endicott Arcade Addition:

# No Adverse Effect with updated conditions








# Shelter Type 1 - 60% Plans

#### 5<sup>th</sup>/Cedar St – in the URHD

6<sup>th</sup>/Jackson St, 6<sup>th</sup>/Minnesota St, and 5<sup>th</sup>/Robert St - adjacent


- Reduced size. Side Platform: 34'8" long and 10'8" wide. Canopy: 47' long, 10'7" wide, and 13'8" tall
- Reduced tilt. Angled bents 1'2" deep. No tilt past back of platform






23

# Shelter Type 1 - 60% Plans



#### Urban Renewal Historic District - 60% Plans




### Urban Renewal Historic District - 60% Finding

#### No Adverse Effect with the following condition

• Shelter finishes are reviewed with consulting parties at the 90% design stage to ensure they meet the SOI Standards.

#### Manhattan, Pioneer Endicott / Endicott Arcade Addition - 60% Plans




### Manhattan, Pioneer Endicott / Endicott Arcade Addition - 60% Finding

#### No Adverse Effect with the following condition

- Construction documents (plans and specifications) are reviewed at each of the remaining design stages (90%, 100%, and any changes made to the 100% plans) to ensure that alternative construction methods recommended to reduce potential for construction-related damage are incorporated.
- Shelter finishes are reviewed with consulting parties at the 90% design stage to ensure they meet the SOI Standards.

## Rice Park/Hamm Plaza Station Area



#### Location: Rice Park and Hamm Plaza





#### Rice Park Historic District: No Adverse Effect with updated conditions

## Rice Park /Hamm Plaza Station Area



#### Hamm Building: No Adverse Effect with updated conditions


U.S. Post Office, Court House and Custom House (Landmark Center): No Adverse Effect with updated conditions



## Shelter Type 2 - 60% Plans

#### **Rice Park Station**


Smallest size. Side
Platform: 27'3" long and
10'8" wide. Canopy: 27'3"
long, 10'7" wide, and 13'5"
tall




 Reduced tilt. Angled bents 1'2" deep. No tilt past back of platform




## Shelter Type 2 - 60% Plans



## Rice Park Historic District - 60% Plans




## Landmark Center - 60% Plans




**Rice Park Station** 

### Landmark Center - 60% Plans



## Hamm Building - 60% Plans



36

### Rice Park Historic District, Landmark Center, and Hamm Building - 60% Findings

#### No Adverse Effect with the following condition

• Shelter finishes are reviewed with consulting parties at the 90% design stage to ensure they meet the SOI Standards.

## Next Steps

- Consulting Party Review June 2 August 2, 2021
- 90% Plan Review September November 2021
  - Design to include detail on shelter finishes
  - CRU staff and CRU's consultant will review plans to confirm there are no substantive changes
  - Consultation on remaining conditions will occur with consulting parties (~October 2021)

## Questions/Comments?

For more information: <u>www.metrotransit.org/gold-line-project</u>

#### METRO Gold Line BRT Project Office Chelsa Johnson, Environmental Lead Chelsa.Johnson@metrotransit.org

MnDOT Cultural Resources Unit Consultant Kristen Zschomler, Section 106 Lead <u>kristen.zschomler@meadhunt.com</u>