




	Culvert Crossing
_	Railroad
	10 ft Contour <sup>1</sup>



Brickyard Trail

Brickyard Access Trail

Paved Trail

Ravine/Stream Channel Included in Study

Clay Pit Wall

Study Limits



Potential for Slope Failure (or Slope Failure Risk)

> High Medium

> > Low



200 Feet

POTENTIAL FOR SLOPE FAILURE (BASED ON JULY 2014 SITE CONDITIONS) Brickyard Area of Lilydale Regional Park St. Paul, Minnesota

FIGURE 3-2

<sup>1</sup> 10 ft contours derived from 2011 DNR LiDAR.