

1. Trail connection to Keller Regional Park
 • Trail connection is not clear
 • Excessive paving in area



2. Round Lake trail
 • Trail provides access to nice views of lake
 • Some erosion at lake access points



3. Trail along East Shore Drive
 • Narrow, shared trail
 • No protection from vehicles in some locations
 • Becomes congested on busy days



4. Southeast side of Round Lake
 • No trail access to this area
 • Very picturesque area



5. Picnic Pavilion Area
 • Lots of trails converge in this area
 • Trails are not clearly marked with their destination
 • Confusing which is bike and pedestrian trail



6. High Point - East Side of Lake
 • Steep trails access the highest point in park
 • Some nice filtered views of the lake from this vantage point




7. Trail along Wheelock Parkway
 • Trail not wide enough for two way bike traffic




8. Wheelock Parkway bike trails
 • Trail on Wheelock Parkway is not clearly defined



9. Arlington Avenue trail connection
 • Trail connection is not clearly visible



10. Neighborhood connection
 • There is no trail connection under Bruce Vento Regional Trail to adjacent neighborhood



11. South end of Lake Phalen
 • Congestion usually occurs near the parking lot at the south end of the lake