



# CROSBY FARM PARK- PARKING LOT WEST existing conditions



## Crosby Park Parking Lot Study

**existing**  
1.56 acres of impervious surface

existing parking- 53