




Historic Photographs and 1970s Aerial Image of Lilydale Regional Park



Site Photographs and Existing Site Materials




Site Section



Site Connections

Site Investigation



Site Plan 0' 30' 60' 90'

Pavilion Plan 0' 15' 30' 45'

North



Prairie Pathways




Landscape Edges



Site Furnishing



Weathered Steel



Natural Hardwood



Concrete

Site Materials

Pavilion Materials



Site entry view from Parking



View from Pickerel Lake Trail



Pavilion entry from the West



Pickkerel Lake from the Pavilion



View from Pickerel Lake Trail



Pavilion entry from the North