

Minnesota State Capitol Restoration Project

Architectural Integrity. Building Functionality. Life Safety.



mn.gov/capitol-restoration



Minnesota Capitol Restoration



flickr.com/photos/capitol-restoration



@ADMN_Minnesota



A Brief History



- Completed in 1905
- Cass Gilbert, Architect
- Third Minnesota Capitol
- 9 years to build
- Cost: \$4.5 million
- Estimated replacement cost: \$518 million
- National Register of Historic Places since 1972
- \$310 Million to Restore



A Capitol Timeline



1896: Construction begins
1905: Capitol opens
2011: Capitol Preservation Commission
2013: Restoration begins
Fall 2017: Restoration complete



Who Uses the Capitol?



- Governor
- Attorney General
- Legislative Branch
 - 349 Legislators and staff during Session
 - Hundreds of citizens participating in legislative process
- Supreme Court
- Broadcast and print media
- Public events
- 370 Events with 52,392 Attendees
- Historical Society Tours
 - 120,000 Visitors
 - 60,000 Students
 - 1,300 Tours
 - 38,000 Info desk questions



Minnesota's Public Forum



The Minnesota State Capitol is the forum for citizens and elected leaders to debate the issues of the day and plan for tomorrow. It is the symbolic "Peoples' House."





Farmers Holiday Association Relief March - 1933





Anti-war march on the State Capitol - 1970





Property Tax Protest - 1971





National Political Convention Protests - 2008





Marriage Equality Rally – 2013





The Need for Restoration



A Tipping Point

- Crumbling exterior
- Life safety concerns
- Outdated infrastructure:
 OHVAC

 - o Electrical
 - \circ Plumbing
- Not user-friendly to the public.





Interior Deterioration





Marble was crumbling like ... sugar





Exterior Deterioration





- Exterior stone was rapidly deteriorating
- The roof was also in poor shape and leaking





Priceless art was damaged







Crowded hallways and hearing rooms made public involvement difficult





Approval and Funding of the Restoration



Moving the process forward: State Capitol Preservation Commission

Creating a process to move forward

Key criteria:

- Detailed history of need
- Stakeholders had to be involved early
- Stakeholders had to be project owners
 - Could not be a "department project"
- Authority to take actions
- Ability to continue despite electoral changes
- Created constituency for the Capitol





Guiding Principles for Restoration



Architectural Integrity

- Preserve essential design elements.
- Be true to Cass Gilbert's 1905 vision.



Life Safety

- Accessible to all Minnesotans and visitors.
- Updated safety codes.
- Secure infrastructure.



Building Functionality

• Serve government functions for the next 100 years.


These principles guide all work and decision making.





Phases of Project Work





Phases	Date Began
Basement abatement, demolition, and construction	September 2013
Preparation and construction of mechanicals, electrical systems, and plumbing	February 2014
Closure of Capitol: Ground and 1 st Floors of West Wing and Entire East Wing	June 2014
Close and repair 2 nd and 3 rd Floors of the West Wing and entire North Wing	June 2015



Life Safety Improvements

	Life Safety	
Current	ltem	Planned
0 %	Safe Fresh Air Intakes	100 %
40 %	Area of Building Protected by Fire Sprinklers	90 %
0 %	Area of Building Served by Exhaust Ventilation	65 %
0 %	Area of Building Served by New Plumbing	100 %
0	Enclosed Exit Stairs	1
0	Exit Stairs with Direct Access to Exterior	5




Fire protection





Emergency exits and stairwells







Building Functionality

- Increased seating/accessibility features in hearing rooms
- Public meeting rooms
- Additional restrooms
- Visitor Center
- Classroom
- Expanded dining options



Restored hearing rooms have more public space





Future Cass Gilbert Room







After



New small conference room





New public meeting room













Architectural Integrity Rediscovered Treasures!





Uncovered skylight in Supreme Court Courtroom





Future public space in basement under Rotunda.





Historic mosaic tile uncovered and restored





Restored architectural elements







Exterior Marble Work





Marble repair and restoration





Marble repair and restoration






Marble repair and restoration





Restored column with new and old marble





Restored decorative marble carvings





Blending in new marble






Before and after: Restored detail work






Roof and Dome Repair






Roof replacement





Roof restoration: Demolition






Roof restoration: New pavers






Restoration and Repair House and Senate Chambers





House Chamber





House Chamber





House Chamber





Senate Chamber





Restoration and Repair Stained Glass







Historic skylight restoration





Historic skylight restoration






Historic skylight restoration





West Grand Staircase





Restoration and Repair Rotunda





Rotunda:

- Water damage repair
- Ventilation/Mechanicals
- Fine art restoration





Rotunda Chandelier





Tight Quarters





Rotunda Art Restoration






Painting and regilding at the top of the Rotunda





Before and After: Art Restoration





Restoration and Repair Plaza Stairs and Grounds





South Steps and Plaza





Aurora Avenue





Restoration and Repair Decorative Art






















Restoration and Repair Fine Art





Supreme Court mural restorations





Senate Chamber mural restorations






East Grand Stairs restoration





Supreme Court Chamber: "The Moral and Divine Law" (1905) Chamber





Fall 2017 Grand Opening Celebration!



You're invited to the Grand Opening Celebration! Fall 2017

- Enjoy a once-in-a-lifetime experience
- Free
- Activities for all ages and interests
- Rediscover <u>your</u> Capitol



